

SANLORENZO 100SL — SANLORENZO



Builder: SANLORENZO

LOA: 100' (30.48mm)

Year Built: 1998

Model: Motor Yacht

Price: \$2,200,000 USD

Location: United States

Our experienced yacht broker, Andrey Shestakov, will help you choose and buy a yacht that best suits your needs **Sanlorenzo 100SL — SANLORENZO** from our catalogue. Presently, at **Shestakov Yacht Sales Inc.**, we have a wide variety of yachts available on our sale's list. We also work in close contact with all the big **yacht manufacturers** from all over the world.

If you would like to buy a yacht **Sanlorenzo 100SL — SANLORENZO** or would like help answering any questions concerning purchasing, selling or chartering a yacht, please call **+1(954)274-4435**

TABLE OF CONTENTS

TABLE OF CONTENTS	2
SPECIFICATIONS	3
Overview	3
Basic Information	6
Dimensions	6
Accommodations	6
Hull and Deck Information	7
Engine Information	7
PHOTOS	8
51afb300-7031-4491-b5d0-536745d70424	8
f7c3ceb6-c57d-4cee-8000-3faf8383c12c	8
CONTACTS	9
Contact details	9
Telephones	9
Office hours	9
Address	9

SPECIFICATIONS

Overview

Preliminary Listing

Additional Specs & Photos Coming Soon

"Cariloy" is a four-stateroom raised pilothouse motor yacht with separate crew quarters. The yacht is maintained by a permanent professional crew of four. There is an established planned maintenance program adhered to by the crew. In addition to planned maintenance, the yacht has undergone regular major refits. The highlight of these refits was a complete re-power carried out at Bradford Marine in 2014.

Refit Work

The 2020/21 refit carried out at Broward Marine in Dania Beach cost approximately \$2,000,000

Broward Marine 2020/21

- 1) Major service of generators and main engines
- 2) Service and repair main battery banks
- 3) Clean all tanks and replace senders
- 4) Renew bilge pumps
- 5) Renew engine room ventilation
- 6) Re-build fuel purifiers
- 7) New deck plates for machinery spaces
- 8) New machinery space lighting
- 9) New laundry area
- 10) Install new fan coil units
- 11) Refurbish steering, hydraulic pumps, rudder bearings
- 12) Re-furbish trim tabs and machinery
- 13) New shafts and stern seals
- 14) Repair/refurbish propellers

- 15) Re-build stabilizers
- 16) Re-furbish/re-build all load handling equipment (davit, windlasses and winches)
- 17) New fresh water tanks
- 18) Re-build fresh water pumps
- 19) Re-new interior and exterior lighting
- 20) New underwater lighting
- 21) Re-furbish teak deck
- 22) Install new teak cap rails
- 23) New navigation electronics
- 24) New CCTV system
- 25) Complete new galley
- 26) Re-furbish/re-new crew mess
- 27) Re-furbish tender and RIB dinghy
- 28) Re-paint entire yacht
- 29) Re-paint anti-fouling paint

Bradford Marine 2014

- 1) Service fuel purifiers
- 2) Propellers balanced
- 3) Fuel tank repairs
- 4) Replace engines and transmissions
- 5) Remove and replace all exterior doors for fair and paint
- 6) Replace and re-bed rudder bolts
- 7) Upgrade fresh water system
- 8) Service and repair windlasses
- 9) Renew interior floor panels
- 10) Work to modify engine room for new propulsion package and subsequent

alignment

- 11) New flybridge helm console
- 12) New engine wiring harnesses
- 13) Modify engine room stringers for new engines
- 14) New engine room sound insulation and perforated metal
- 15) Machine polish and hand wax all exterior paint
- 16) Engine controls modifications and replacements
- 17) New stabilizer and bow thruster oil coolers
- 18) Replace engine room deck plates and framing
- 19) Repair Atlas shore power system
- 20) New engine exhaust system
- 21) Change toilets from sea water to fresh water flush
- 22) New shaft bearings
- 23) Install new generators
- 24) New engine propeller shafts
- 25) New underwater lights

The 2006/2007 refit by Rybovich in West Palm Beach cost approximately \$1,000,000 and the 2014 refit by Bradford Marine in Fort Lauderdale cost approximately \$3,200,000

Rybovich 2006/2007

- 1) Main engines serviced.
- 2) Both generators re-built
- 3) Fuel tanks cleaned
- 4) New battery chargers and re-configure battery system
- 5) Service stabilizers
- 6) New bilge pumps

- 7) New air compressor
- 8) New shore power selector
- 9) Replace hot water heaters
- 10) New water maker filters and housings
- 11) New washer/dryers
- 12) New flybridge canvas
- 13) New steering pumps
- 14) New outside grill
- 15) New swim ladder
- 16) New inverter for satellite TV
- 17) New interior carpets
- 18) New galley and flybridge fridges and freezers
- 19) Complete new exterior paint
- 20) Maintenance and service to remaining systems and equipment

Basic Information

Category: Motor Yacht

Model Year: 1998

Year Built: 1998

Country: United States

Dimensions

LOA: 100' (30.48mm)

Accommodations

Total Cabins: 4

Hull and Deck Information

Hull Material: Fiberglass

Engine Information

Engines: 2

Manufacturer: Caterpillar

Engine Type: Inboard

Fuel Type: Diesel

PHOTOS

**51afb300-7031-4491-b5d0-
536745d70424**



**f7c3ceb6-c57d-4cee-8000-
3faf8383c12c**



CONTACTS

Andrey Shestakov, leading yacht broker of the sales department of Shestakov Yacht Sales Inc. Shestakov Yacht Sales Inc., the official representative of the Miami/Fort Lauderdale FL headquarters.

Contact details

Email: **andrey@shestakovyachtsales.com**

Web: shestakovyachtsales.com/en/

Telephones

USA: **+1(954)274-4435**

Office hours

Monday – Saturday: **9:00 - 21:00** EDT

Sunday: **closed**

Address



Harbour Towne Marina, 850 NE 3rd St, STE 213, Dania, FL 33004