

STRIKE FORCE — STRIKER



Builder: <u>STRIKER</u> **LOA**: 44' 0" (13.41m)

Year Built: 1974 **Beam**: 15' 9" (4.80m)

Model: Motor Yacht Max Draft: 3' 9" (1.14m)

Price: PRICE ON APPLICATION Cruise Speed: 21 Kts. (24 MPH)

Location: Honduras **Max Speed**: 26 Kts. (30 MPH)

Our experienced yacht broker, Andrey Shestakov, will help you choose and buy a yacht that best suits your needs **Strike Force** — **STRIKER** from **our catalogue**. Presently, at **Shestakov Yacht Sales Inc.**, we have a wide variety of yachts available on **our sale's list**. We also work in close contact with all the big **yacht manufacturers** from all over the world.

If you would like to buy a yacht **Strike Force** — **STRIKER** or would like help answering any questions concerning purchasing, selling or chartering a yacht, please call **+1(954)274-4435**

Strike Force — STRIKER Page 2 of 11

TABLE OF CONTENTS

TABLE OF CONTENTS	2
SPECIFICATIONS	4
Basic Information	4
Dimensions	4
Speed, Capacities and Weight	4
Accommodations	4
Hull and Deck Information	4
Engine Information	5
DETAILED INFORMATION	6
Accommodations	6
Salon and Interior	6
Galley	6
Electronics	6
Electrical System	7
Engine Room and Mechanical	7
BRIDGE	7
Cockpit and Fishing Equipment	8
Deck and Miscelaneous Equipment	8
Exclusions	9
Disclaimer	9
PHOTOS	10
Haul out for bottom job	10
At the dock in Roatan	10
Haul out for bottom job	10
New bottom job	10
Starboard view	10
At the dock in Roatan	10
CONTACTS	11

Strike Force — STRIKER Page 3 of 11

Contact details	11
Telephones	11
Office hours	11
Address	11

Strike Force — STRIKER Page 4 of 11

SPECIFICATIONS

Basic Information

Category: Motor Yacht Model Year: 1974

Year Built: 1974 Country: Honduras

Dimensions

LOA: 44' 0" (13.41m) **Beam**: 15' 9" (4.80m)

Max Draft: 3' 9" (1.14m)

Speed, Capacities and Weight

Cruise Speed: 21 Kts. (24 MPH) Max Speed: 26 Kts. (30 MPH)

Displacement: 22000 Pounds Water Capacity: 100 Gallons

Fuel Capacity: 735 Gallons

Accommodations

Total Cabins: 2 **Total Heads**: 2

Hull and Deck Information

Hull Material: Aluminum

Strike Force — STRIKER Page 5 of 11

Engine Information

Engines: 2 Manufacturer: Cummins

Model: 6CTA8.3M Engine Type: Inboard

Fuel Type: Diesel

Strike Force — STRIKER Page 6 of 11

DETAILED INFORMATION

Accommodations

From the cockpit walk through sliding glass doors to the main salon with L shaped settee to port and leather sofa to stbd. with entertainment center forward. The salon is large and spacious with teak woodwork and carpeting. From the salon walk down three steps to the full galley with upright refrigerator, cook top, microwave, ice maker, stainless sink and lots of cabinets and drawer space. Across from the galley to port is the master stateroom with twin berths and access to private head and shower. Walking forward to the V berth are upper and lower bunks to port with storage cabinets to stbd. and forward head.

Salon and Interior

- Carpeting throughout
- L shaped settee to port with leather couch to stbd.
- Entertainment center with LG flat screen TV, Sony stereo and CD player
- (3) Mermaid A/C units
- Uline ice maker
- Coffee table
- Electrical panel in salon
- Raritan toilets/MSD system
- Teak joiner work throughout
- Two stateroom/two head layout
- 110V/12V lighting throughout
- Reading lights at berths

Galley

- Full size refrigerator
- 2 burner cooktop
- Microwave
- Stainless sink
- Ample cabinets and drawer storage

Electronics

- Horizon Intrepid VHF
- ICOM IC-M56 VHF
- ICOM IC-M6000 SSB

Strike Force — STRIKER Page 7 of 11

- Northstar 952X GPS
- Furuno FCV-582L Bottom machine
- JRC FF 10 bottom machine
- Furuno 64 mile Radar
- Autohelm ST7000 Auto pilot
- Danforth 5" Compass
- ACR 406 EPIRB

Electrical System

- TDEC 11 KW Genset
- 110V AC/12V DC Service
- Two Marinco 50' Shore cords (30amp)
- 12V/120V Lighting throughout
- Raritan 40 amp battery charger
- Engine room lighting
- (4) 8D Gel Cell batteries
- Main Electrical panel in salon with Sub panel on bridge

Engine Room and Mechanical

- Twin Cummins 6CTA8.3-M Diesels w/ZF IRA280A transmissions (450HP) 675 Hrs.
- Three integral fuel tanks with man holes and dip sticks
- Racor fuel filters
- Hynautic hydraulic steering
- Hynautic hydraulic engine controls
- Fire Boy Clean agent fire suppression system
- Raritan head/MSD system
- Hot and cold fresh water system with Groco pump and accumulator tank
- Dripless shaft logs
- Seaward 6 gal. Water heater
- Two Aguamet 22 2" stainless shafts
- Two 28" X 34" 4 blade Nibral props
- Two 8" sea chests with Marlon valves
- Five (5) Rule bilge pumps

BRIDGE

- Helm console with Hynautic steering and engine controls, full engine instrumentation, electronics and switching
- Two (2) Helm chairs

Strike Force — STRIKER Page 8 of 11

- Cushioned bench seating with storage below
- Aft bridge rails with rod holders
- Windshield
- Teaser reels
- Remote for search light (mounted on tower)
- Horn
- Flybridge ladder to cockpit
- Access to tower
- Danforth compass

Cockpit and Fishing Equipment

- Tackle center
- Rod holders
- Transom door
- Gin pole
- Fighting chair
- Rupp triple spreader outriggers (Black with Gold)
- Center rigger
- Teak covering boards
- Eskimo ice machine
- Cockpit bait freezer
- Full tower (New 2001) with steering and controls, bench seat and sun shade

Deck and Miscelaneous Equipment

- Spectra water maker
- Integral aluminum bow rails (painted)
- Awlgrip paint
- Integral cleats and hawse holes
- Pulpit
- Three (3) Bomar deck hatches
- Life raft mounted on foredeck
- Integral fuel tanks with man hole access and dip sticks
- Two (2) Danforth anchors
- Ideal windlass
- Awlgripped non-skip fore and side decks
- Hull color white with black striping and gold accent
- Fresh bottom paint (2013)
- Spreader lights
- Helm and fighting chair covers

Strike Force — STRIKER Page 9 of 11

Exclusions

Owner's personal belongings.

Disclaimer

The Company offers the details of this vessel or yacht in good faith but cannot guarantee or warrant the accuracy of this information nor warrant the condition of the vessel. A buyer should instruct his representatives, agents, or his surveyors, to investigate such details as the buyer desires validated. This vessel or yacht is offered subject to prior sale, price change, or withdrawal without notice.

Strike Force — STRIKER Page 10 of 11

PHOTOS

Haul out for bottom job	At the dock in Roatan
Haul out for bottom job	New bottom job
Starboard view	At the dock in Roatan

Strike Force — STRIKER Page 11 of 11

CONTACTS

Andrey Shestakov, leading yacht broker of the sales department of Shestakov Yacht Sales Inc. Shestakov Yacht Sales Inc., the official representative of the Miami/Fort Lauderdale FL headquarters.

Contact details

Email:

Web: shestakovyachtsales.com/en/

andrey@shestakovyachtsales.com

Telephones

USA: +1(954)274-4435

Office hours

Monday - Saturday: **9:00 - 21:00** EDT Sunday: **closed**

Address



Harbour Towne Marina, 850 NE 3rd St, STE 213, Dania, FL 33004